


CNC part alignment (non-CAD)



© 2013 Renishaw plc. All rights reserved.

Renishaw® is a registered trademark of Renishaw plc.

This document may not be copied or reproduced in whole or in part, or transferred to any other media or language, by any means, without the prior written permission of Renishaw.

The publication of material within this document does not imply freedom from the patent rights of Renishaw plc.

Disclaimer

Considerable effort has been made to ensure that the contents of this document are free from inaccuracies and omissions. However, Renishaw makes no warranties with respect to the contents of this document and specifically disclaims any implied warranties. Renishaw reserves the right to make changes to this document and to the product described herein without obligation to notify any person of such changes.

Trademarks

All brand names and product names used in this document are trade names, service marks, trademarks, or registered trademarks of their respective owners.

CNC part alignment (non-CAD)

Care of equipment

Renishaw probes and associated systems are precision tools used for obtaining precise measurements and must therefore be treated with care.

Changes to Renishaw products

Renishaw reserves the right to improve, change or modify its hardware or software without incurring any obligations to make changes to Renishaw equipment previously sold.

Warranty

Renishaw plc warrants its equipment for a limited period (as set out in our Standard Terms and Conditions of Sale) provided that it is installed exactly as defined in associated Renishaw documentation.

Prior consent must be obtained from Renishaw if non-Renishaw equipment (e.g. interfaces and/or cabling) is to be used or substituted. Failure to comply with this will invalidate the Renishaw warranty.

Claims under warranty must be made from authorised service centres only, which may be advised by the supplier or distributor.

Trademarks

Windows 98, Windows XP, Windows 2000 and Windows NT are registered tradenames of the Microsoft Corporation.

IBM is the tradename of the International Business Machines Inc

All trademarks and tradenames are acknowledged.

Contents

1	CNC part alignment (non-CAD)	6
1.1	Tutorial pre-requisites.....	6
1.2	Tutorial objectives.....	6
2	Introduction.....	7
3	Measuring a plane in 'Program (CNC)' mode.....	8
4	Measuring circles in 'Program (CNC)' mode	12
5	Creating a three axis datum	17

1 CNC part alignment (non-CAD)

1.1 Tutorial pre-requisites

- The student should understand the contents of the 'Principles of part alignment' tutorial
- The student should have completed 'Part alignment - plane, line and point' tutorial and 'Part alignment - plane and two circles' tutorial

1.2 Tutorial objectives

- Introduction to the creation of CNC part programs
- Understand CNC machine motion and measurement principles and options
- Further exposure to programming from drawing definition

2 Introduction

The manual alignments that have been covered so far are too crude for good metrology. This is because they don't take enough points and there are significant errors.

However, these rough alignments can be used as a starting point from which more precise alignments can be achieved.


In this tutorial, CNC mode will be used to precisely align the Renishaw training block.

Before starting this tutorial, the component should have been manually aligned as outlined in the 'Part alignment - plans and two circles' tutorial.


3 Measuring a plane in 'Program (CNC)' mode

With a basic manual alignment in place, a more accurate CNC alignment of the component need to be created.


Firstly, the program mode must be set to 'Program CNC':




Following the manual alignment, the probe needs to be withdrawn from the last measured feature into a safe location.




GUIDANCE NOTE: An increment move means the sensor will move a specified distance in the specified direction relative to its current position.







The machine will now move.


The top face can now be measured:




Give the feature a meaningful name i.e. TOP_FACE_DATUM_C.

Plane	TOP_FACE_DATUM_C							
	Actual	Nominal	Low tol	High tol	Deviation	Status	Error	
X axis	0	0			0			


Take eight points on the plane:




Click: 'Apply' to complete the measuring cycle.




With the plane measured a primary datum can be created:




Now move the machine to an 'Absolute' position above the part origin, ready to measure the next feature.



GUIDANCE NOTE: An 'absolute' move defines the end point of a move rather than the direction and distance.



NOTE: Clicking 'Teach' reads the current machine position and updates all 'target' fields. Clicking on 'X', 'Y' or 'Z' updates only the 'target' field associated with that axis.



```


000001
000002 GOTO/INCR,15,0,0,1
000003 GOTO/CART,0,0,10
000004

```



The probe will then move.



4 Measuring circles in 'Program (CNC)' mode

As in earlier manual alignments, the centre of the large bore on the training block will be used as the origin. As such, it must also be measured in 'Program (CNC)' mode.



Since there is already a provisional alignment, the drawing dimensions / nominals can be used to create the points to measure the feature.






Select: 'Apply' to complete the measuring cycle.

The circle will then be measured. Again, the probe needs to be moved out of the feature to prevent collision when moving to measure the next feature.

Click: 'Move' then select 'Absolute'




Enter the co-ordinates to move the probe to a position above the circle to inspect the next feature.


OR

Use the MCU to manually place the probe and then press 'Take Point'.

Next, a hole on the PCD will be measured. In this tutorial, the PCD hole labelled 'circle 2' on the graphic below will be used:



Click: 'Inspect'.



Select: 'Circle'.

Enter label.


Circle	DAT_X_CIR2	Inn
Report	Actual	Nominal
X axis	24.395	24.395
Y axis	24.395	24.395
Z axis	-13	-13
I	0	0
J	0	0
K	1	1
Diameter	7	7

Enter the circle nominal data.


Select: 'Add Touches'.



Select: 'Apply' to complete the measuring cycle.




Circle 2
DAT_X_CIR2



Use the handbox to move probe out of the circle and click 'Take Point' to create a GOTO.

Next, a line will be constructed between the centres of the two measured holes. This feature will then be used to create the datum.

Click: 'Construct'.



Select: 'Line'.



Click: 'Best Fit'.

Double click on feature or drag and drop features into the construction area.

Give the line a label.

Feature	Actual/No.	Point Buffer
DATUM_X_Y	actual	
DAT_X_CIR2	actual	

Line	Actual	Nominal	Low tol	High tol	Deviation	Status	Error
X axis	12.197	12.198			-0		
Y axis	12.197	12.198			-0		
Z axis	-8.5	-8.5			0		
I	0.704	0.704					

Make a note of the order the holes have been inserted in the construction window, i.e. DATUM_X_Y to DAT_X_CIR2 will give a positive direction and DAT_X_CIR2 to DATUM_X_Y will give a negative direction.

This is important when selecting the axis direction for alignment.

Click: 'Apply' to complete the construction cycle.

5 Creating a three axis datum

The three axis datum can now be created:

Click: 'Datum'.

Select: 'Three Axes'.

Assign a label

Enter desired labels to match the drawing:

In this case TOP_FACE_DATUM_C is the PRIMARY AXIS [+Z]
On drawing datum C.

X_LINE is the SECONDARY AXIS [+X] (no origin here)
On drawing datum A

DATUM_X_Y is the TERTIARY Point - origin [X and Y]
On drawing datum B

Click: 'OK' to complete the procedure.

In this case the constructed line lies along the X axis.

NOTE: There is also have the option of selecting -X or +Y/-Y.

Create Datum

Datum label: Aligned_On_X_Line

Primary

Label: C

Feature: TOP_FACE_DATUM_C

Axis: ☒ +X ☐ -X ☐ +Y ☐ -Y ☐ +Z ☐ -Z

Origin: ☐ X ☐ Y ☒ Z

Secondary

Label: A

Feature: X_LINE

☐ Disabled

Axis: ☒ +X ☐ -X ☐ +Y ☐ -Y ☐ +Z ☐ -Z ☐ None

Origin: ☐ X ☐ Y ☐ Z

Tertiary

Label: B

Feature: DATUM_X_Y

☐ Disabled

Origin: ☒ X ☒ Y ☐ Z

OK Cancel

Now check if both circles are in the correct positions.


Left mouse click on DATUM_X_Y
The grid will display the result both X and Y should be at zero.



Left mouse click on DAT_X_CIR2
The grid will display the result X = 34.500 : Radial distance From DATUM_X_Y
Y = 0.00.



As shown in the diagram below, the current datum needs to be rotated about the Z axis to achieve the required alignment.





Now make a theoretical rotation using the defined angle through the two co-ordinates given i.e:

$X = 24.395$ and $Y = 24.395$



Angle = $\text{Inv Tan} (24.395 / 24.395) = 45^\circ$

In this case the X and Y axes need to be rotated clockwise by 45° .

NOTE: -ve angles give clockwise rotation, +ve angles give anti-clockwise rotation.



Now check if both circles are in the correct positions.



Renishaw plc
New Mills, Wotton-under-Edge,
Gloucestershire, GL12 8JR
United Kingdom

T +44 (0)1453 524524
F +44 (0)1453 524901
E uk@renishaw.com
www.renishaw.com

RENISHAW 
apply innovation™

**For worldwide contact details,
please visit our main web site at
www.renishaw.com/contact**



H - 1000 - 5315 - 01